

From: [GAINER Tom](#)
To: [YOUNG Cyril](#)
Cc: [ANDERSON Jim M](#); [Eric Blischke/R10/USEPA/US@EPA](#)
Subject: RE: Alder Creek Lumber ECSI ID 2446
Date: 06/24/2008 10:02 AM

Cy-

I'm not seeing much sediment data immediately adjacent to Alder Creek Lumber Site (the southern tip of Sauvie Island at RM 3) in the Rd. 2 Report, but I caution that I am not as immersed in the in-water data as others working on the project. The LWG did not identify this area as an iAOPC, but I would check with Jim Anderson and Eric Blischke to confirm the existence of any data and potential cleanup plans for this area.

Thanks-
Tom

-----Original Message-----

From: YOUNG Cyril
Sent: Monday, June 23, 2008 9:41 AM
To: GAINER Tom
Subject: RE: Alder Creek Lumber ECSI ID 2446

No need to review the sediment data, we have a lease with Alder Creek and they are talking about possibly terminating the lease. Our concern is how much clean up may be needed fronting their site. I've looked at the LWG sampling and it doesn't appear to be a area of extreme concern, just wanted to check with DEQ, see if you had any additional data. Thanks

From: GAINER Tom [mailto:Tom.Gainer@state.or.us]
Sent: Monday, June 23, 2008 9:30 AM
To: YOUNG Cyril
Subject: RE: Alder Creek Lumber ECSI ID 2446

I'm not aware of any further upland site evaluation, but there may be some additional in-water sediment analyses near the site since the Weston report. I have attached the 12/20/99 DEQ Strategy recommendation based on the Weston report. Please let me know if you want me to review current sediment data, which would take a little while.

Thanks-
Tom

-----Original Message-----

From: YOUNG Cyril
Sent: Thursday, June 19, 2008 9:22 AM
To: GAINER Tom
Subject: Alder Creek Lumber ECSI ID 2446

Tom,

Does DEQ have any more information on Alder Creek Lumber, other than what is on your website? Not much in the ECSI report other than it needed a site screening and the Weston report identified it as part of their Portland Harbor Sediment Study. Specifically, what contaminants have been identified in the sediments, if any? Thanks

Cyril J. (CY) Young

Land Manager - Portland Harbor

Linn, Benton and Lane Counties
Dept. of State Lands
775 Summer St NE, Suite 100
Salem, OR 97301-1279
503-986-5245 (NEW NUMBER)
cyril.young@dsl.state.or.us
fax 503-378-4844